Appendix III

Photo Micrographs

Listing of Photographs

All Photographs unless otherwise noted are at 100x

1) Before photo of L-10 surface.

2) After photo showing damage of L-10. 30 J/cm^2

3) Laser damage on part L-10.40 J/cm^2.

4) Before photograph of L-10 surface

5) After photo showing damage of L-10. 40J/cm^2 .

6) Catastrophic Damage on L-10.

7) Laser damage on part L-11 40 J/cm^2

8) Before showing scatter site L-11.

9) After photo showing damage of L-11. 40 J/cm^2.

10) Before showing scatter site L-11.

11) After photo showing damage L-11. 40 J/cm^2.

12) Subsurface laser damage part L-12. 45 J/cm^2 .

13) Subsurface laser damage part L-12. 30 J/cm^2 .

14) Surface laser damage part L-12. 40 J/cm^2.

15) -17) Surface of L-13.

18) Subsurface damage L-17. 40 J/cm^2.

19) Subsurface damage L-17. 35 J/cm^2.

1



2



3



4



6



5

7



8



9



10



11



12



17



18



19



1



2



3



4



6



5



7



8



9



10



11



12



13



14



15



16



17



18



19